

System requirements

Audio&Video Products

The table below lists Yealink products compatible with DSPs from Yealink partners in the Yealink Pro AV solution, along with the required minimum versions of these products:

| Product | Applicable Version |
|---------|--------------------------------|
| UVC84 | Version 262.430.0.20 and above |
| UVC86 | Version 151.430.0.20 and above |
| AVHub | Version 153.430.0.20 and above |

For all models that have been verified for compatibility through Yealink testing, please refer to [DSP Compatible List](#).

Yealink RoomConnect

The supported Yealink RoomConnect version is 2.30.50.0 and above. To obtain the latest software, please refer to [Release Note](#).

Yealink | Support

TicketWarranty ServiceLicenseKnowledge BaseResource CenterPrime CareHelp Desk

EN | 中dxt_Yealink

More Modules

Teams Devices

Search by title

Content

Teams Video Phone & Audio Phone

MeetingBar A10/A20/A30

Microsoft Teams Rooms System (MVC)

Release Note

Datasheet

Deployment & Connection

Quick Start

User Guide

Administrator Guide

Technical References

Security Whitepaper

Video Center

MeetingBoard 65&86

DeskVision A24

Home > Knowledge Base > Teams Devices > Microsoft Teams Rooms System (MVC) > Release Note

Release Note

Last Update Time: 2023-09-27Pageviews: 3583

Download PDFShareFavoriteSubscribe

September 2023

Latest Firmware Versions

MTouch Plus/MTouch E2: 282.410.0.25 upgraded to 282.432.0.5 [Download Firmware](#)

AV Hub: 153.431.0.25 upgraded to 153.432.0.5 [Download Firmware](#)

UVC86: 151.431.0.15 upgraded to 151.432.0.5 [Download Firmware](#)

Yealink RoomConnect: 2.31.67.0 upgraded to 2.32.42.0 [Download Firmware](#)

Points for Attention

- Renamed S90 Multi-Speaker Tracking to Multi-Camera Intelliframe.
- Optimized S90 Multi-Camera Intelliframe, YRC, AVHub, and UVC86 need to be upgraded to the latest version if new features are to be used.
- Introduced MVC860 wireless BYOD function, if you need to use it, please with the WPP update to 30.270.352.0.75. When WPP30 access to the computer is prompted to update the software, please agree to update.
- MTouch Plus supports the RoomSensor energy saver program and is required to be used with RoomSensor version 8.510.0.50. RoomSensor will be automatically upgraded after MTouch Plus is updated.

| No. | Description | Model | Related Topic |
|-----|--|--------------|--|
| 1 | Added Video Fence function, when the function is turned on, users can limit the scope of the AI function. | UVC86 | Video Fence |
| 2 | Introduced camera default tracking function setting, administrators can set the camera's default tracking function. If user switches the tracking mode during a meeting, the camera will automatically revert to the default tracking mode after the meeting is over. | UVC86 | |
| 3 | Introducing the wireless BYOD feature that allows users to conduct meetings on their own PCs using the audio and video hardware in the room. | UVC86, WPP30 | WPP30 Supports Wireless BYOD |
| 4 | Optimize the multi-speaker tracking function, the maximum number of people covered by a single camera of UVC86 rises from 3 to 6, which reduces the deployment cost, Optimize the way of configuring the camera coverage area, which is more intuitive to be configured on the screen of the UVC86 sub-lens. | AVHub, UVC86 | Multi-camera Intelliframe |

Contents

September 2023

April 2023

November 2022

April 2022

Copyright © 2023 Yealink Inc. All rights reserved.

Privacy Policy | Cookies Management